WATERS

ASSET



KPDES #	Facility	Water Quality To	reatement Center Receiving	Stream of Treatment Center	Region	
KY0098540	ID MSD0289	CEDAR CREEK		CEDAR CREEK	NA	
Facility Type	Facility ID	Facility Address	If Pump Station, Name of Pump Statio	n: Receiving Stream	Discharge to	
SMNSewer Main	103399-V	3100 TUCKER STATIO	N RD	CHENOWETH RUN	GROUND	

SMNSewer Main	103399-V		3100 TUCKE	ER STATION RD				CHENOWETH RUN	GROUND
Activity Code / Description	WO # Ref No	<u>Initiated</u>	Initiated By	Assigned To	Disch Status	Event Date	<u>Problem</u>	Result	Completed Condition
: DISDW: DRY WEATHER	3334945	01/11/2021	GOODWIN	MSD	REPAIRED -	01/11/2021	UTILITY	UNAUTHORIZED	01/11/21 07:55
DISCHARGE				CONTRACTO	ISSUE		DAMAGED MSD	DISCHARGE-	PM

Discharge Reporting:

z.com.gomoponung.	
Discharge Amount:	24,000 GAL
Cause:	CONTRACTOR DAMAGED MSD ASSET/FORCEMAIN.
Clean Up:	MSD DISINFECTED AREA WITH LIME.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWER FOUND ON GROUND.
Repair:	CALLED TRC TO REPAIR BREAK, HAULING DOMINION WAY AND TUCKERS LAKE PS.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

RESOLVED

1/11/21 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	\prod
1/11/21 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION	



KPDES # Facility Water Quality Treatement Center Receiving Stream of Treatment Center Region

KY0098540 MSD0289 CEDAR CREEK NA

Facility Type Facility ID Facility Address If Pump Station, Name of Pump Station: Receiving Stream Discharge to

SMHSewer Manhole 28506 11301 ELECTRON DR CHENOWETH RUN DITCH

Activity Code / Description WO # Ref No **Initiated** Initiated By **Assigned To Disch Status Event Date Problem** Result Completed Condition : DISDW: DRY WEATHER 3342474 02/05/21 11:40 02/05/2021 BIVIN BIVIN REPAIRED -02/05/2021 OBSTRUCTION-UNAUTHORIZED DISCHARGE ISSUE NOT GREASE / DISCHARGE-AM **RESOLVED** ROOTS WATERS MI

Discharge Reporting:

Discharge Amount:	300 GAL
Cause:	DAMAGE IN MAIN.
Clean Up:	MSD WILL CLEAN AREA.
Control Zone:	MSD ADVISED CUSTOMER TO AVOID SEWAGE CONTACT.
Impact:	OBSERVED MH# 28506 DISCHARGING
Repair:	PLACED TVI INSPECTION ON THE MAIN POSSIBLE FIBER OPTIC DAMAGE BORED THROUGH MAIN, FLUSHED MAIN AND MANHOLE
Public Notification:	DISCHARGE SIGN PLACED AROUND AREA.

2/6/21 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	
----------------	--------	---	--

MI



Facility Water Quality Treatement Center Receiving Stream of Treatment Center KPDES# Region

MSD0278 MORRIS FORMAN NA KY0022411

Facility Type Facility ID **Facility Address** If Pump Station, Name of Pump Station: **Receiving Stream** Discharge to

SMHSewer Manhole 29341 2409 PLANTSIDE DR CHENOWETH RUN **STREAM**

Activity Code / Description WO # Ref No **Initiated** Initiated By **Assigned To Disch Status Event Date Problem** Result Completed **Condition** 01/06/21 01:33 : DISDW: DRY WEATHER 3334378 01/06/2021 BIVIN BIVIN REPAIRED -01/06/2021 OBSTRUCTION-UNAUTHORIZED

NOT GREASE / DISCHARGE-

DISCHARGE **ISSUE** PM **RESOLVED** ROOTS WATERS

Discharge Reporting:

z io ciiai go i top ci aii gi	
Discharge Amount:	250 GAL
Cause:	OBSTRUCTION.
Clean Up:	MSD CLEANED AREA.
Control Zone:	MSD ADVISED CUSTOMER TO AVOID SEWAGE CONTACT.
Impact:	OBSERVED DISCHARGE FROM MH# 29341 FLUSHED MANHOLE DISCOVERED BOTTOM GONE OUT OF MANHOLE
Repair:	MANHOLE REPAIR AND CLEANED.
Public Notification:	CALL AND DISCHARGE SIGNS.

1/7/21 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	
----------------	--------	---	--



KPDES # Facility Water Quality Treatement Center Receiving Stream of Treatment Center Region

KY0022411 MSD0278 MORRIS FORMAN NA

Facility TypeFacility IDFacility AddressIf Pump Station, Name of Pump Station:Receiving StreamDischarge toSMHSewer ManholeCSO020147 BUCHANAN STOHIO RIVERSTREAM

Activity Code / Description WO # Problem POWER Ref No **Initiated** Initiated By **Assigned To Disch Status Event Date** Result Completed Condition 03/21/2021 : DISDW: DRY WEATHER 3359754 FRENCH FRENCH REPAIRED -03/21/2021 UNAUTHORIZED 03/21/21 03:21 DISCHARGE

ISSUE OUTAGE (LG&E) DISCHARGE- PM
RESOLVED WATERS

Discharge Reporting:

RY WEATHER NOTIFICATION

3/22/21 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	
3/22/21 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION	



KPDES # Facility Water Quality Treatement Center Receiving Stream of Treatment Center Region

KY0098540 MSD0289 CEDAR CREEK NA

Facility Type Facility ID Facility Address If Pump Station, Name of Pump Station: Receiving Stream Discharge to SLSSewer Lift Station MSD1185-PS 6810 ARBOR MANOR WAY ARBOR MANOR CEDAR CREEK DITCH

Activity Code / Description WO #

: DISDW: DRY WEATHER 3351847 Ref No Initiated **Initiated By Disch Status Event Date Problem** Result Completed Condition Assigned To MECHANICAL UNAUTHORIZED 03/08/2021 GRAY JR KOHR JR REPAIRED -03/08/2021 03/09/21 12:00 DISCHARGE ISSUE **FAILURE** DISCHARGE-AM RESOLVED WATERS

Discharge Reporting:

- · · · · · · · · · · · · · · · · · · ·	
Discharge Amount:	300 GAL
Cause:	FAILURE IN ARV.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/WATER DISCHARGING FROM MANHOLE.
Repair:	VALVE WAS SHUT OFF.
Public Notification:	GIVEN BY VOLUNTARY EMAIL NOTIFICATION SYSTEM.

Notifications:

	OTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, DENNIS@EPAMAIL.EPA.GOV
--	---

Total Facilities Printed: 5

Total Work Orders Printed: 5