



700 West Liberty Street | Louisville, KY 40203-1911  
Phone: 502.540.6000 | LouisvilleMSD.org

February 19, 2024

Crystal Dennis  
300 Sower Blvd., 3rd Floor  
Frankfort, Kentucky 40601

**RE: Cedar Creek WQTC, KPDES No: KY0098540  
Discharge Monitoring Report for January 2024.**

Dear Mrs. Dennis:

Attached are the Discharge Monitoring Report (DMR) and the Monthly Operator Report (MOR) for the Cedar Creek WQTC, for the month of January 2024.

Also attached is overflow report.

There were no bypasses or exceedances.

If you have any questions concerning the attached DMR's, please contact me at (502)540-6717.

Sincerely,

Jon Baldrige  
Process Supervisor

JOB/ Cedar Creek. 01/24.

Enclosures

Cc: V. Graves  
B. Tinnell



81011	Solids, suspended percent removal	K - Percent Removal	0	--	Sample	=	98.0										23 - %	01/30 - Monthly	CA - CALCTD			
					Permit Req.	>=	85.0 MO AV MN													23 - %	01/30 - Monthly	CA - CALCTD
					Value NODI																	

**Submission Note**

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

**Edit Check Errors**

No errors.

**Comments**

**Attachments**

Name	Type	Size
CCOverflow.pdf	pdf	60663.0
cedarcreek.pdf	pdf	36391.0
CCMOR012024.XLS	xls	340992.0

**Report Last Saved By**

**Cedar Creek WQTC MSD**

User: JON.BALDRIDGE@LOUISVILLEMSD.ORG  
 Name: Jonathan Baldrige  
 E-Mail: jon.baldrige@louisvillemsd.org  
 Date/Time: 2024-02-20 13:01 (Time Zone: -05:00)

**Report Last Signed By**

User: JON.BALDRIDGE@LOUISVILLEMSD.ORG  
 Name: Jonathan Baldrige  
 E-Mail: jon.baldrige@louisvillemsd.org  
 Date/Time: 2024-02-20 13:07 (Time Zone: -05:00)



**IMSAST0004**  
**Overflow Report**  
**1/1/2024 12:00:00 AM to 1/31/2024 12:00:00 AM**

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0098540	MSD0289	CEDAR CREEK	CEDAR CREEK	NA

  

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Treatment Plant	MSD0289	8405 CEDAR CREEK RD	CEDAR CREEK	CEDAR CREEK	GROUND

  

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW:DRY WEATHER DISCHARGE	3751747		1/31/2024 6:10:00 PM	BALDRIDGE		REPAIRED - ISSUE RESOLVED	1/31/2024 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE-WATERS	01/31/24 06:10 PM	

**Discharge Reporting:**

Discharge Amount:	2,000 GAL
Cause:	PARTIAL BLOCKAGE IN PLANT DRAIN LINE. DRAINING CLARIFIER INTO DRAIN LINE.
Clean Up:	LIME PLACED ON PATH OF SLUDGE FLOW.
Control Zone:	N/A
Impact:	SLUDGE ON GROUND.
Repair:	EIC FLUSHED AND VACTORED DRAIN LINE.
Public Notification:	SIGNS PLACE ALONG CREEK.

**Notifications:**

2/1/24 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	---