

700 West Liberty Street | Louisville, KY 40203-1911 Phone: 502.540.6000 | LouisvilleMSD.org

April 18, 2024

Crystal Dennis 300 Sower Blvd., 3rd Floor Frankfort, Kentucky 40601

RE: Pioneer Village STP, KPDES No: KY0034185 Discharge Monitoring Report for March 2024.

Dear Ms. Dennis:

Attached are the Discharge Monitoring Report (DMR) for the Pioneer Village STP, for the month March 2024.

There were no overflows, bypass, or exceedances.

Also attached is the Monthly Discharge Report.

If you have any questions concerning the attached DMR's, please contact me at (502) 540-6717.

Sincerely,

Jon Baldridge Process Supervisor

JOB/ PV 3/24.

Cc: V. Teague /B. Tinnell

DMR Copy of Record

Permit		

KY0034185 Permit #:

Louisville and Jefferson County MSD Permittee:

Major: No 700 W Liberty St Louisville, KY 40203

PIONEER VILLAGE SEWER PLANT #1

Permittee Address:

DMR Due Date:

Facility Location: 12600 MORNINGSIDE DR LOUISVILLE, KY 40229

Facility:

Permitted Feature: 001

External Outfall

Discharge: 001-1 Domestic Wastewater

Report Dates & Status

Monitoring Period: From 03/01/24 to 03/31/24

04/28/24

Status: **NetDMR Validated**

Considerations for Form Completion

Principal Executive Officer

First Name: James A. Title: **Executive Director** Telephone: 502-540-6000

Last Name: Parrott

No Data Indicator (NODI) Form NODI:

	Parameter	Monitoring Location Seas	ion Season # Param. NODI			Quantity or Loading					Quality or Concentration					# of Ex	. Frequency of Analysis	s Sample Type
Code	Name				Qualifier 1	Value 1	Qualifier 2	Value 2	Units Qualifier	1 Value 1	Qualifier 2	2 Value 2	Qualifier 3	3 Value 3	Units			
				Sample					=	8.0					19 - mg/L		01/30 - Monthly	GR - GRAB
00300	Oxygen, dissolved [DO]	1 - Effluent Gross 0		Permit Req.					>=	7.0 INST MIN	ı				19 - mg/L	0	01/30 - Monthly	GR - GRAB
				Value NODI														
				Sample					=	7.2			=	7.2	12 - SU		01/30 - Monthly	GR - GRAB
00400	Н	1 - Effluent Gross 0		Permit Reg.					>=	6.0 MINIMUM	1		<=	9.0 MAXIMUM	12 - SU		,	GR - GRAB
00400	рп	1 - Elliuelit Gloss 0		Value NODI												U		
				Sample							<	6.0	<	6.0	19 - mg/L		,	CP - COMPOS
00530	Solids, total suspended	1 - Effluent Gross 0		Permit Req.							<=	30.0 MO AVG	<=	45.0 MX WK AV	19 - mg/L	0	01/30 - Monthly	CP - COMPOS
				Value NODI														
				Sample							=	12.2	=	12.2	19 - mg/L		01/30 - Monthly	CP - COMPOS
00600	Nitrogen, total [as N]	1 - Effluent Gross 0		Permit Req.								Req Mon MO AVO	3	Req Mon DAILY MX	19 - mg/L	0	01/30 - Monthly	CP - COMPOS
00000	ratiogen, total [as 14]	1 Emachi Oloss 0		Value NODI														
				Sample							=	0.2	=	0.2	19 - mg/L		01/30 - Monthly	CP - COMPOS
				Permit Reg.							= <=	10.0 MO AVG	<=	15.0 DAILY MX	19 - mg/L		,	CP - COMPOS
00610	Nitrogen, ammonia total [as N]	s N] 1 - Effluent Gross 2									_	10.0 WO AVG	_	13.0 DAILT WX	19 - Hig/L	0	01/30 - Monthly	CI - COIVII OS
				Value NODI														
				Sample							=	1.75	-	1.75	19 - mg/L		01/30 - Monthly	CP - COMPOS
00665	Phosphorus, total [as P]	1 - Effluent Gross 0		Permit Req.								Req Mon MO AVO	3	Req Mon DAILY MX	19 - mg/L	0	01/30 - Monthly	CP - COMPOS
				Value NODI														
				Sample	= 0	.372	=	0.479	03 - MGD								01/30 - Monthly	IN - INSTAN
50050		1 - Effluent Gross 0		Permit Reg.		teq Mon MO AVO		Reg Mon MX WK AV								0	,	IN - INSTAN
50050	Flow, in conduit or thru treatment plant	1 - Elliuent Gloss 0		Value NODI		•										U	•	
				Sample								0.01		0.01	19 - mg/L		,	GR - GRAB
50060	Chlorine, total residual	1 - Effluent Gross 0		Permit Req.							<=	0.011 MO AVG	<=	0.019 DAILY MX	19 - mg/L	0	01/30 - Monthly	GR - GRAB
				Value NODI														
				Sample							=	40.0	=	136.0	13 - #/100mL		01/30 - Monthly	GR - GRAB
51040	E. coli	1 - Effluent Gross 0		Permit Req.							<=	130.0 30DA GEO	<=	240.0 7 DA GEO	13 - #/100mL	. 0	01/30 - Monthly	GR - GRAB
31040	L. 60II	1 - Lilluciit Gioss 0		Value NODI												U		
												4.0		1.0	10 ma/l		01/20 Monthly	CP - COMPOS
				Sample Permit Reg.							<=	4.0 15.0 MO AVG	<=	4.0 22.5 MX WK AV	19 - mg/L 19 - mg/L		,	CP - COMPOS
80082	BOD, carbonaceous [5 day, 20 C]	1 - Effluent Gross 0									<=	13.0 IVIO AVG	<=	ZZ.J IVIA VVR AV	19 - IIIg/L	0	0 1/30 - MOHUITY	CF - COIVIFUS
				Value NODI														

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

Attachments

Type

03_March_2024_All_Services_Area_fin.pdf		pdf	1258121.0
PV.pdf		pdf	36975.0
Report Last Saved By			
Louisville and Jefferson County MSD			
User:	JON.BALDRIDGE@LOUISVILLEMSD.ORG		
Name:	Jonathan Baldridge		
E-Mail:	jon.baldridge@louisvillemsd.org		
Date/Time:	2024-04-18 08:58 (Time Zone: -04:00)		
Report Last Signed By			
User:	JON.BALDRIDGE@LOUISVILLEMSD.ORG		
Name:	Jonathan Baldridge		
E-Mail:	jon.baldridge@louisvillemsd.org		
Date/Time:	2024-04-18 09:01 (Time Zone: -04:00)		



KPDES#	Facility ID	Water 0	Quality Treatm	ent Center	Center Recieving Steam of Discharge			Region				
KY0040126	MSD0411	KSR			CEDAR CREEK	<	NA					
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Statio	on	Recieving St	ream	Discharge To			
Sewer Main	122738-CO	2040 C	COX LN	KSR			DARBY CREE	ΞK	GROUND			
Activity Code / Description	WO#	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition	
DISDW:DRY WEATHER DISCHARGE	3777443		3/29/2024 12:00:00 PM	BUTLER 1	SOSA RODRIGUEZ	REPAIRED - ISSUE RESOLVED	3/29/2024 12:00:00 AM	STRUCTURAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	03/29/24 10:19 PM		

Discharge Amount:	5,850 GAL
Cause:	STRUCTURAL FAILURE - FORCE MAIN BREAK.
Clean Up:	MSD CONTRACTOR TO CLEAN AND SANITIZE THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE PRODUCTS FOUND ON THE GROUND.
Repair:	REPAIRED THE FORCEMAIN WO#3777436.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

3/29/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/29/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water 0	Quality Treatm	ent Center	r Recieving Steam of Discharge			Region						
KY0022411	MSD0278	MORRI	MORRIS FORMAN					NA						
Facility Type	Facility ID	Facility	Address	If Pump Station	, Name of Statio	n	Recieving St	ream	Discharge To					
Sewer Manhole	28249	3500 S DR	ST EDWARDS	MORRIS FORM	AN		CHENOWET	H RUN	DITCH					
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition			
DISREV:RAIN EVENT DISCHARGE	3767616		3/6/2024 7:55:00 AM	DAVIS BROWN	BAILEY	DOCUMENTED	3/12/2006 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/06/24 02:33 PM	MAIN			

Discharge Amount:	102,500 GAL
Cause:	LACK OF SYSTEM CAPACITY HEAVY RAIN.
Clean Up:	WO#3767688.
Control Zone:	CAUTION TAPE, TEMPORARY DISCHARGE SIGNS, AND BARRICADE PLACED AROUND THE IMPACTED AREA.
Impact:	MANHOLE DISCHARGING.
Repair:	LOCATION INCLUDED IN IOAP.
Public Notification:	PUBLIC NOTIFIED THROUGH DOOR HANGERS AND TEMPORARY SIGNS AT DISCHARGE SITE TO AVOID CONTACT WITH DISCHARGED CONTENT.

Notifications:

3/6/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/6/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water 0	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region							
KY0022411	MSD0278	MORRI	MORRIS FORMAN					NA						
Facility Type	Facility ID	Facility	Address	If Pump Station	, Name of Statio	on	Recieving St	ream	Discharge To					
Sewer Manhole	28250	3506 (PKY	CHARLANE	MORRIS FORM	AN		CHENOWETI	H RUN	DITCH					
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition			
DISREV:RAIN EVENT DISCHARGE	3767613		3/6/2024 7:45:00 AM	DAVIS BROWN	BAILEY	DOCUMENTED	1/3/2005 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/06/24 02:33 PM	MAIN			

Discharge Amount:	102,500 GAL
Cause:	LACK OF SYSTEM CAPACITY HEAVY RAIN.
Clean Up:	WO#3767687.
Control Zone:	CAUTION TAPE, TEMPORARY DISCHARGE SIGNS, AND BARRICADE PLACED AROUND THE IMPACTED AREA.
Impact:	MANHOLE DISCHARGING.
Repair:	LOCATION INCLUDED IN IOAP.
Public Notification:	PUBLIC NOTIFIED THROUGH DOOR HANGERS AND TEMPORARY SIGNS AT DISCHARGE SITE TO AVOID CONTACT WITH DISCHARGED CONTENT.

Notifications:

3/6/24 1:00 F	М	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/6/24 1:00 F	M	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water 0	Water Quality Treatment Center			Recieving Steam of Discharge Region							
KY0022411	MSD0278	MORRI	MORRIS FORMAN					NA					
Facility Type	Facility ID	Facility Address If Pump Station, Name of Station				n	Recieving Stream Discharge To						
Sewer Manhole	28336	3620 (PKY					CHENOWETI	H RUN	DITCH				
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition		
DISREV:RAIN EVENT DISCHARGE	3767617		3/6/2024 8:00:00 AM	DAVIS BROWN	BAILEY	DOCUMENTED	8/30/2005 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/06/24 02:35 PM	MAIN		

Discharge Amount:	20,500 GAL
Cause:	LACK OF SYSTEM CAPACITY HEAVY RAIN.
Clean Up:	WO#3767692
Control Zone:	CAUTION TAPE, TEMPORARY DISCHARGE SIGNS, AND BARRICADE PLACED AROUND THE IMPACTED AREA.
Impact:	MANHOLE DISCHARGING.
Repair:	LOCATION INCLUDED IN IOAP.
Public Notification:	PUBLIC NOTIFIED THROUGH DOOR HANGERS AND TEMPORARY SIGNS AT DISCHARGE SITE TO AVOID CONTACT WITH DISCHARGED CONTENT.

Notifications:

3/6/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/6/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water 0	Water Quality Treatment Center			Recieving Steam of Discharge Region							
KY0022411	MSD0278	MORRI	MORRIS FORMAN					NA					
Facility Type	Facility ID	Facility Address If Pump Station, Name of Station				n	Recieving Stream Discharge To						
Sewer Manhole	28340	3620 (PKY				ıN CH		H RUN	GROUND				
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition		
DISREV:RAIN EVENT	3767660		3/6/2024 7:55:00 AM	DAVIS BROWN	BAILEY	DOCUMENTED	1/3/2005 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-	03/06/24 02:35 PM	MAIN		

Discharge Amount:	41,000 GAL
Cause:	LACK OF SYSTEM CAPACITY HEAVY RAIN.
Clean Up:	WO#3767691.
Control Zone:	CAUTION TAPE, TEMPORARY DISCHARGE SIGNS, AND BARRICADE PLACED AROUND THE IMPACTED AREA.
Impact:	MANHOLE DISCHARGING.
Repair:	LOCATION INCLUDED IN IOAP.
Public Notification:	PUBLIC NOTIFIED THROUGH DOOR HANGERS AND TEMPORARY SIGNS AT DISCHARGE SITE TO AVOID CONTACT WITH DISCHARGED CONTENT.

Notifications:

3/7/24	1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/7/24	1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water C	Water Quality Treatment Center			Recieving Steam of Discharge Region						
KY0022411	MSD0278	MORRIS	S FORMAN				NA					
Facility Type	Facility ID	Facility Address If Pump Station, Name of Station				on	Recieving Stream Discharge To					
Sewer Manhole	28451	3406 C PKY				CHENOWETH RUN			GROUND			
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition	
DISREV:RAIN EVENT	3767611		3/6/2024 7:40:00 AM	DAVIS BROWN	BAILEY	DOCUMENTED	10/28/2015 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/06/24 02:30 PM	MAIN	

Discharge Amount:	102,500 GAL
Cause:	LACK OF SYSTEM CAPACITY HEAVY RAIN.
Clean Up:	WO#3767686.
Control Zone:	CAUTION TAPE, TEMPORARY DISCHARGE SIGNS, AND BARRICADE PLACED AROUND THE IMPACTED AREA.
Impact:	MANHOLE DISCHARGING.
Repair:	LOCATION INCLUDED IN IOAP.
Public Notification:	PUBLIC NOTIFIED THROUGH DOOR HANGERS AND TEMPORARY SIGNS AT DISCHARGE SITE TO AVOID CONTACT WITH DISCHARGED CONTENT.

Notifications:

3/6/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/6/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water 0	Water Quality Treatment Center			Recieving Steam of Discharge Region							
KY0022411	MSD0278	MORRI	MORRIS FORMAN					NA					
Facility Type	Facility ID	Facility Address If Pump Station, Name of Station				on	Recieving Stream Discharge		Discharge To				
Sewer Manhole	28452	3402 C PKY					CHENOWETI	H RUN	DITCH				
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition		
DISREV:RAIN EVENT DISCHARGE	3767610		3/6/2024 7:35:00 AM	DAVIS BROWN	BAILEY	DOCUMENTED	11/30/2019 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/06/24 07:30 PM	MAIN		

Discharge Amount:	34,000 GAL
Cause:	LACK OF SYSTEM CAPACITY HEAVY RAIN.
Clean Up:	WO#3767685.
Control Zone:	CAUTION TAPE, TEMPORARY DISCHARGE SIGNS, AND BARRICADE PLACED AROUND THE IMPACTED AREA.
Impact:	MANHOLE DISCHARGING.
Repair:	LOCATION INCLUDED IN IOAP.
Public Notification:	PUBLIC NOTIFIED THROUGH DOOR HANGERS AND TEMPORARY SIGNS AT DISCHARGE SITE TO AVOID CONTACT WITH DISCHARGED CONTENT.

Notifications:

3/6/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/6/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water 0	Water Quality Treatment Center			Recieving Steam of Discharge Region							
KY0022411	MSD0278	MORRI	MORRIS FORMAN					NA					
Facility Type	Facility ID	Facility Address If Pump Station, Name of Station				n	Recieving Stream Discharge To						
Sewer Manhole	28453	3402 (PKY	CHARLANE	MORRIS FORM	AN		CHENOWETH RUN		DITCH				
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition		
DISREV:RAIN EVENT DISCHARGE	3767608		3/6/2024 7:30:00 AM	DAVIS BROWN	BAILEY	DOCUMENTED	10/28/2015 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/06/24 07:30 PM	MAIN		

Discharge Amount:	10,800 GAL
Cause:	LACK OF SYSTEM CAPACITY HEAVY RAIN.
Clean Up:	WO#3767684.
Control Zone:	CAUTION TAPE, TEMPORARY DISCHARGE SIGNS, AND BARRICADE PLACED AROUND THE IMPACTED AREA.
Impact:	MANHOLE DISCHARGING.
Repair:	LOCATION INCLUDED IN IOAP.
Public Notification:	PUBLIC NOTIFIED THROUGH DOOR HANGERS AND TEMPORARY SIGNS AT DISCHARGE SITE TO AVOID CONTACT WITH DISCHARGED CONTENT.

Notifications:

3/6/24 1:00 PM		EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/6/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water Quality Treatment Center			Recieving Steam of Discharge Region							
KY0022411	MSD0278	MORRIS	S FORMAN				NA					
Facility Type	Facility ID	Facility	Facility Address If Pump Station, Name of Station				Recieving Stream Discharge To				,	
Sewer Lift Station	MSD0125-PS	3602 T RD				LITTLE GOOS	SE CREEK	STREAM				
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition	
DISDW:DRY WEATHER DISCHARGE	3776324		3/21/2024 3:39:00 PM	SANTEE	SANTEE	REPAIRED - ISSUE RESOLVED	3/21/2024 12:00:00 AM	MECHANICAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	03/21/24 05:40 PM		

Discharge Amount:	500 GAL
Cause:	ELECTRICAL PROBLEM WITH MSD EQUIPMENT, PUMP CONTROLLER FAULTED.
Clean Up:	AREA DISINFECTED WITH LIME.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND IN THE DITCH.
Repair:	REPAIRED THE PUMP CONTROLLER.
Public Notification:	PAGE SENT.

Notifications:

3/22/24 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
-----------------	--------	---



KPDES#	Facility ID	Water 0	Water Quality Treatment Center			am of Discharge	Region						
KY0022411	MSD0278	MORRI	MORRIS FORMAN					NA					
Facility Type	Facility ID	Facility	Facility Address If Pump Station, Name of Station					Recieving Stream Discharge To					
Sewer Treatment Plant	MSD0278	4522 <i>F</i> PKY	4522 ALGONQUIN MORRIS FORMAN PKY				OHIO RIVER STREAM						
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition		
DISDW:DRY WEATHER DISCHARGE	3765924		3/4/2024 1:25:00 PM	BURDIN		REPAIRED - ISSUE RESOLVED	3/4/2024 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	03/04/24 02:30 PM			

Discharge Amount:	19,500 GAL
Cause:	PRIMARY REHAB PROJECT CONSTRUCTION CREW STRUCK LINE
Clean Up:	PUMPED TO PRIMARY, SOME ESCAPED TO WUS, OHIO RIVER VIA STORM DRAIN.
Control Zone:	PERMANENT SIGN AT OUTFALL.
Impact:	NONE.
Repair:	ISOLATED AND VALVED LINE.
Public Notification:	NONE.

Notifications:

3/5/24 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/5/24 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water 0	Water Quality Treatment Center			Recieving Steam of Discharge Region					
KY0034169	MSD0507	BCSD H	BCSD HILLVIEW #2								
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Treatment Plant	MSD0507	386 NO			IEW #2		BROOKS RUN		STREAM		
Activity Code / Description	WO#	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3767549		3/6/2024 3:35:00 AM	BALDRIDGE		DOCUMENTED	12/6/2021 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-	03/06/24 09:30 AM	

Discharge Amount:	10,800 GAL
Cause:	LACK OF CAPACITY.
Clean Up:	CLEANED UP CONCRETE DITCH DEBRIS.
Control Zone:	INSIDE OF PLANT FENCE.
Impact:	INF DISCHARGING TO CONCRETE DITCH ON PLANT.
Repair:	FLOW WENT DOWN FROM RAIN EVENT, INF PUMPS WERE ABLE TO CATCH UP.
Public Notification:	TEMPORARY SIGN NEAR FENCE BY DISCHARGE.

Notifications:

3/6/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/6/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water Quality Treatment Center			Recieving Stea	m of Discharge	Region				
KY0034185	MSD0512	PIONE	ER VILLAGE #1	I	BROOKS RUN						
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Treatment Plant	MSD0512	815 JO HWY	0.0 00				BROOKS RU	N	STREAM		
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3768206		3/9/2024 7:40:00 AM	BALDRIDGE		QUEUED FOR INVESTIGATIO N / REPAIR	3/7/2023 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/11/24 07:09 AM	

Discharge Amount:	10,200 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NONE NEEDED.
Control Zone:	AT PLANT.
Impact:	INF DISCHARGING TO EFF MANHOLE.
Repair:	SET UP TEMPORARY TRASH PUMP TO HELP PUMP DOWN IPS.
Public Notification:	TEMP SIGN NEAR FENCE.

Notifications:

3/9/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/9/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water Quality Treatment Center			Recieving Stea	m of Discharge	Region				
KY0022420	MSD0202	HITE CREEK			HITE CREEK	HITE CREEK NA					
Facility Type	Facility ID	Facility Address If Pump Station			, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Lift Station	MSD1109-PS	6120 HITE CREEK CHAMBERLAIN LN			WOLF PEN B	RANCH	GROUND				
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW:DRY WEATHER DISCHARGE	3767745		3/7/2024 8:24:00 AM	SANTEE	SANTEE	REPAIRED - ISSUE RESOLVED	3/24/2024 12:00:00 AM	MECHANICAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	03/07/24 01:30 PM	

Discharge Amount:	1,000 GAL
Cause:	MECHANICAL FAILURE, TILT BULB ON BIOMAT.
Clean Up:	MSD CONTRACTOR CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND IN THE DITCH.
Repair:	MSD CONTRRACTOR VACTORING BIOMAT FROM WELL.
Public Notification:	PAGE SENT.

Notifications:

Motifications.		
3/7/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/7/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water Quality Treatment Center			Recieving Stea	m of Discharge	e Region				
KY0022420	MSD0202	HITE CREEK			HITE CREEK	HITE CREEK NA					
Facility Type	Facility ID	Facility Address If Pump Statio		n, Name of Station		Recieving Stream Disc		Discharge To		,	
Sewer Lift Station	MSD1109-PS	00	ERLAIN LN	HITE CREEK			WOLF PEN B	RANCH	GROUND		
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW:DRY WEATHER DISCHARGE	3776584		3/24/2024 9:35:00 PM	SANTEE	SANTEE	REPAIRED - ISSUE RESOLVED	3/24/2024 12:00:00 AM	MECHANICAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	03/25/24 07:12 AM	

Discharge Amount:	1,000 GAL
Cause:	ELECTRICAL PROBLEM WITH MSD EQUIPMENT, PHASE MONITOR FAULT/ SCADA ISSUES.
Clean Up:	MSD CONTRACTOR CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND IN THE DITCH.
Repair:	RESET PHASE MONITOR AND SOFT STARTERS.
Public Notification:	PAGE SENT.

Notifications:

3/25/24 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/25/24 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water Quality Treatment Center		Recieving Stea	ecieving Steam of Discharge Region						
KY0094307	MSD0511	WILLABROOK			BROOKS RUN	ROOKS RUN					
Facility Type	Facility ID	Facility Address If Pump Station		n, Name of Statio	Name of Station Recieving Stream		ream	Discharge To			
Sewer Lift Station	MSD2019-PS	3955 E BLUE LICK WILLABROOK RD				BROOKS RUN		GROUND			
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition

Discharge Amount:	1 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NO IMPACT OBSERVED - FACILITY UNDER ELEVATED CREEK LEVEL.
Repair:	A SOLUTION FOR THIS LOCATION IS INCLUDED IN THE INTEGRATED OVERFLOW ABATEMENT PLAN.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

2/28/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/28/24 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID	Water C	Quality Treatm	ent Center	Recieving Stea	m of Discharge	Region				
KY0094307	MSD0511	WILLAB	ROOK		BROOKS RUN						
Facility Type	Facility ID	Facility	Address	If Pump Station	, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Lift Station	MSD2019-PS	3955 E RD	BLUE LICK	WILLABROOK			BROOKS RUN		GROUND		
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3767538		3/6/2024 7:12:00 AM	BROADEN	BROADEN	QUEUED FOR INVESTIGATIO N / REPAIR	4/6/2022 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	03/06/24 08:08 AM	

Discharge Amount:	9,400 GAL	
Cause:	LACK OF SYSTEM CAPACITY.	
Clean Up:	CLEANUP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL.	
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.	
Impact:	NO IMPACT OBSERVED - FACILITY UNDER ELEVATED CREEK LEVEL.	
Repair:	A SOLUTION FOR THIS LOCATION IS INCLUDED IN THE INTEGRATED OVERFLOW ABATEMENT PLAN.	
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.	

Notifications:

3/6/24 1:00 PM DISNOT EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	
---	--



KPDES#	Facility ID	Water Q	uality Treatm	ent Center	Recieving Stea	am of Discharge	Region				
KY0034185	MSD0512	PIONEE	R VILLAGE #1		BROOKS RUN						
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Static	on	Recieving St	ream	Discharge To		
Sewer Lift Station	MSD2021-PS	165 OC	TAGON AVE	PIONEER VILL	AGE #1		BROOKS RUN		STREAM		
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT	3767536		3/6/2024 7:05:00 AM	BROADEN	BROADEN	DOCUMENTED	12/21/2022 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-	02/29/24 07:47 AM	

Discharge Amount:	1 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE FOUND IN THE STREAM.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

3/6/24 1:00 PM DISNOT EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	
---	--



KPDES#	Facility ID	Water Q	uality Treatm	ent Center	Recieving Stea	m of Discharge	Region				
KY0034185	MSD0512	PIONEE	R VILLAGE #1		BROOKS RUN						
Facility Type	Facility ID	Facility .	Address	If Pump Station	n, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Lift Station	MSD2021-PS	165 OC	TAGON AVE	PIONEER VILL	R VILLAGE #1		BROOKS RUN		STREAM		
Activity Code /	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
Description											

Discharge Amount:	1 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE FOUND IN THE STREAM.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

3/6/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	
----------------	--------	---	--



KPDES#	Facility ID	Water Q	uality Treatm	ent Center	Recieving Stea	m of Discharge	Region				
KY0034185	MSD0512	PIONEE	R VILLAGE #1		BROOKS RUN						
Facility Type	Facility ID	Facility	Address	If Pump Station	, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Lift Station	MSD2021-PS	165 OC	TAGON AVE	PIONEER VILLA	ER VILLAGE #1		BROOKS RUN		STREAM		
Activity Code / Description	WO#	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition

Discharge Amount:	96,300 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE FOUND IN THE STREAM.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

3/9/24 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
3/9/24 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES#	Facility ID Water Quality Treatme		ent Center Recieving Steam of Discharge			Region					
KY0034185	MSD0512	PIONEER VILLAGE #1		BROOKS RUN							
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Lift Station	MSD2021-PS	165 OCTAGON AVE PIONE		PIONEER VILL	EER VILLAGE #1		BROOKS RUN		STREAM		
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN	3770504		3/15/2024	SANTEE	SANTEE	DOCUMENTED	12/21/2022	LACK OF SYSTEM	UNAUTHORIZED	03/12/24	

Discharge Amount:	1 GAL	
Cause:	LACK OF SYSTEM CAPACITY.	
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.	
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.	
Impact:	SEWAGE FOUND IN THE STREAM.	
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.	
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.	

Notifications:

3/15/24 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV	
-----------------	--------	---	--



KPDES#	Facility ID Water Quality Treatmen		ent Center Recieving Steam of Discharge			Region					
KY0034185	MSD0512	PIONEER VILLAGE #1		BROOKS RUN							
Facility Type	Facility ID	Facility	Address	If Pump Station	, Name of Statio	n	Recieving St	ream	Discharge To		
Sewer Lift Station	MSD2021-PS	165 OCTAGON AVE PIONEER VI		PIONEER VILL	LAGE #1		BROOKS RUN		STREAM		
Activity Code / Description	WO#	Ref#	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
	3770674		3/15/2024	SOSA	SOSA	DOCUMENTED	12/21/2022	LACK OF SYSTEM	UNAUTHORIZED	03/16/24	

Discharge Amount:	18,600 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE FOUND IN THE STREAM.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

3/16/24 1:00 PM DISNOT EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV		
--	--	--